

Red John Pumped Storage Hydro Scheme

Environmental Impact Assessment Report
Volume 3: Figures

ILI (Highlands PSH) Ltd.

November 2018

Prepared for:

ILI (Highlands PSH) Ltd.

Prepared by:

Catherine Anderson
EIA Project Manager
T: 0131 301 8600
E: RedJohnPSH@Aecom.com

AECOM Limited
1 Tanfield
Edinburgh EH3 5DA
United Kingdom

T: +44 131 301 8600
aecom.com

© 2018 AECOM Infrastructure & Environment UK Limited. All Rights Reserved.

This document has been prepared by AECOM Infrastructure & Environment UK Limited ("AECOM") for sole use of our client (the "Client") in accordance with generally accepted consultancy principles, the budget for fees and the terms of reference agreed between AECOM and the Client. Any information provided by third parties and referred to herein has not been checked or verified by AECOM, unless otherwise expressly stated in the document. No third party may rely upon this document without the prior and express written agreement of AECOM.

Volume 3: Figures Table of Contents

1. Introduction

- Figure 1.1: Location Plan
- Figure 1.2: The Development Site

2. Project Description

- Figure 2.1: The Surrounding Environment
- Figure 2.2: Utilities
- Figure 2.3: The Development Layout
- Figure 2.4: The Development Layout - Below Ground
- Figure 2.5: The Development Layout - Above Ground
- Figure 2.6: Headpond - Indicative Arrangement
- Figure 2.7: Headpond Embankment
- Figure 2.8: Headpond Embankment Cross-sections
- Figure 2.9: Indicative Embankment Sections
- Figure 2.10: Indicative Headpond Inlet / Outlet Structure
- Figure 2.11: Tailpond Inlet / Outlet Structure Operational
- Figure 2.12: Indicative Tailpond Inlet / Outlet Screen
- Figure 2.13: Tailpond Inlet / Outlet Structure construction
- Figure 2.14: Cross-section of the Development
- Figure 2.15: Indicative Power Cavern Section
- Figure 2.16: Waterways and Tunnels Section
- Figure 2.17: Access Tunnel Portal
- Figure 2.18: Construction Tunnel Portal
- Figure 2.19: Compound 1 - Indicative Layout Construction Phase
- Figure 2.20: Compound 1 - Indicative Layout Operational Phase
- Figure 2.21: C1064 Realignment Indicative Arrangement
- Figure 2.22: Permanent Access Track
- Figure 2.23: Temporary Access Track
- Figure 2.24: Public Road Crossing 1
- Figure 2.25: Public Road Crossing 3 and 4
- Figure 2.26: Indicative Grid Connections

3. Evolution of Design and Alternatives

- Figure 3.1: Design I: Pre-Feasibility
- Figure 3.2: Design II: Feasibility
- Figure 3.3: Design III: Scoping Option A
- Figure 3.4: Design III: Scoping Option B
- Figure 3.5: Design IV: Post Scoping
- Figure 3.6: Design V: Post Public Consultation

Figure 3.7: Design VI: Design Refinement

4. Limits of Deviation

- Figure 4.1: Limits of Deviation

5. Geology and Ground Conditions

- Figure 5.1.: Topography
- Figure 5.2: Bedrock Geology
- Figure 5.3: Superficial Geology
- Figure 5.4: SI Works
- Figure 5.5: Site Visit Features and Peat Probes
- Figure 5.6: Peat Surface

6. Terrestrial Ecology

- Figure 6.1: Ecology Field Survey Areas
- Figure 6.2: Bat Activity Survey
- Figure 6.3: Motion Sensitive Camera Trap Locations
- Figure 6.4: Great Crested Newt Survey
- Figure 6.5: Reptile Survey Areas
- Figure 6.6: Butterfly, Dragonfly and Damselfly Transects
- Figure 6.7: Ancient Woodland
- Figure 6.8: Phase 1 Habitat Survey Results
- Figure 6.9: National Vegetation Classification
- Figure 6.10: GWDTE and Peat Bog
- Figure 6.11: Main Juniper Locations and Veteran Pines
- Figure 6.12: Confirmed bat Roosts
- Figure 6.13: Otter Survey Results
- Figure 6.14: Pine Marten Survey Results
- Figure 6.15: Red Squirrel Survey Results
- Figure 6.16: Reptile Survey Results
- Figure 6.17: Butterfly Observations
- Figure 6.18: Dragonfly Observations
- Figure 6.19: Damselfly Observations

8. Ornithology

- Figure 8.1: Ornithology Survey Areas
- Figure 8.2: Red-listed Passerine Territories
- Figure 8.3: Crested tit and Crossbill Territories
- Figure 8.4: Amber-listed Passerine Territories
- Figure 8.5: Wader Territories
- Figure 8.6: Waterbodies Within 1 km of Development

Figure 8.7: Red-throated Diver Nest Locations

- Figure 8.8: Black Grouse Lek Locations
- Figure 8.9: Barn Owl Roost Location

9. Flood Risk and Water Resources

- Figure 9.1: Significant Water Features
- Figure 9.2: Hydrological Catchments

10. Water Environment

- Figure 10.1: Surface Water and Groundwater Receptors and Attributes - Wider Context
- Figure 10.2: Surface Water and Groundwater Receptors and Attributes - Study Area
- Figure 10.3: Walkover Survey Photos

11. Landscape and Visual

- Figure 11.1: Landscape Designations
- Figure 11.2: Landscape Character Types
- Figure 11.3: Landscape Character Photographs
- Figure 11.4: Zone of Theoretical Visibility (ZTV)
- Figure 11.5: Recreational Routes and Core Paths
- Figure 11.6: Representative viewpoints + ZTV

12. Forestry

- Figure 12.1: Forestry Study Area
- Figure 12.2: Age Class Structure
- Figure 12.3: Baseline Species Composition
- Figure 12.4: Opportunities and Constraints
- Figure 12.5: Development Felling Plan
- Figure 12.6: Woodland Restructuring Plan
- Figure 12.7: Land Use Change

13. Archaeology and Cultural Heritage

- Figure 13.1: Known Archaeology

14. Socio-economics and Tourism

- Figure 14.1: Socio-economic and Tourism Receptors

15. Traffic and Transport

- Figure 15.1: Study Network and Traffic Count Points

16. Noise and Vibration

- Figure 16.1: Noise Sensitive Receptors
- Figure 16.2: Noise Monitoring Locations